

# EPA Risk Management Program





Ellen Banner - USEPA Region 2 Edison New Jersey


## Basic Goal of RMP Program

Reduce the likelihood of accidental chemical releases by using hazard assessments, prevention programs and emergency response planning



## Regulatory Approach

- Congress passed the Clean Air Act Amendments of 1990
- Required EPA to publish regulations and guidance for chemical accident prevention
- Risk Management Plan Rule (RMP Rule) was implemented by EPA in 1999.



## Regulatory Approach

- Rule built upon industry standards and codes as is the OSHA Process Safety Management (PSM) standard implemented in 1990
- Regulations found in 40 C.F.R § 68
- Requires companies that use flammable and toxic substances to develop a Risk Management Plan which includes:

## Elements of RMP

#### **Hazard Assessment:**

Predicts the potential effects of an accidental release through the development of worst case and alternative case scenarios and records any accident history within the past five years

## RMP Element

#### **Prevention Program:**

The most comprehensive RMP element -

Can include safety information & procedures, equipment maintenance & monitoring, employee and contractor training, accident investigation, and the safe management of change.

### RMP Element

#### **Emergency Response**

Spells out emergency health care, employee training measures and procedures for informing local responders and the public


Describes the Emergency Response Plan for the facility including first responder training and response equipment maintenance.

## Do I Need an RMP?

You are subject to the rule if:

\*You have more than a threshold quantity (TQ) of a listed substance in a process.

\*Consolidated List of Subject to the stance of the control of the substance in a process.



http://www.epa.gov/ceppo/pubs/title3.pdf

## Do I need an RMP?


- A process is: "Any activity involving a regulated substance, including any use, storage, manufacturing, handling or on-site movement of such substances, or combination of these activities.
- For the purposes of this definition, any group of vessels that are interconnected, or separate vessels that are located such that a regulated substance could be involved in a potential release, shall be considered a single process"

## Covered Facilities Include:

Chemical manufacturers
Drinking water systems
Wastewater treatment works
Ammonia refrigeration systems
Utilities
Federal facilities
Petroleum Refineries
Agricultural chemicals; and
Nitrogen fertilizers

## Widely Used RMP Chemicals

- Anhydrous Ammonia (threshold Q = 10,000#):
  - used for refrigeration: Food storage, processing.
  - and as a fertilizer: Farm cooperatives
- Chlorine (threshold Q = 2,500#):
  - drinking water treatment
  - wastewater treatment
  - generally stored in 150 lb or 1-ton cylinders



## What's my Program Level?

#### Program Level 1:

Process with no public receptors within the distance to endpoint from a worst case release, no accidents with specific offsite consequences within past 5 years

## What's my Program Level?

#### - Program Level 2:

Processes not eligible for Program 1 or subject to Program 3 are placed in Program 2 which imposes a streamlined prevention program

#### Program Level 3:

Processes not eligible for Program 1 - and either subject to OHSA's PSM standard under federal or state OSHA programs or in ten specified NAICS codes are automatically Program 3


## Specified NAICS Codes

- 32211 pulp mills
- 325181 alkalies and chlorine
- 325188 all other industrial inorganics
- 325211 plastics and resins
- 325192 other cyclic crude & intermediate manufacturing

## Specified NAIC Codes – cont'd

- 325199 all other basic organic chemical manufacturing
- 325311 nitrogen fertilizers
- 32532 pesticide & other agricultural chemicals
- 32411 petroleum refineries
- 32511 petrochemical manufacturing

#### EVALUATE PROGRAM LEVELS FOR COVERED PROCESSES



#### Summary of New York State RMP Facilities by NAICS Sectors


Sector#		Number of Processes	Number of Facilities
221	Utilities	194	86
325	Chemical Manufacturing	281	46
311	Food Manufacturing	35	24
454	Nonstore Retailers (Propane Facilities)	34	17
422	Wholesale Trade, Nondurable Goods	20	14
493	Warehousing and Storage	40	14
326	Plastics and Rubber Products Manufa	8	8
332	Fabricated Metal Product Manufactur	9	5
312	Beverage and Tobacco Product Manuf	4	4
331	Primary Metal Manufacturing	15	4
562	Waste Management and Remediastion	4	4
111	Crop Production	5	3
322	Paper Manufacturing	7	2
334	Computer and Electronic Product Man	5	2
327	Nonmetallic Mineral Product Manufac	1	1
333	Machinery Manufacturing	2	1
481	Air Transportation	1	1
482	Rail Transportation	1	1
812	Personal and Laundry Services	1	1
	Grand Totals:	667	232

## How do I Submit?

- For general guidance, go to: http://www.epa.gov/emergencies/content/ rmp/index.htm#preparinFg
- For a submittal checklist, go to: http://www.epa.gov/OEM/docs/chem/ RMP\_checklist.pdf

#### New system: RMP\*eSubmit

RMP Submission via the Internet



#### Central Data Exchange (CDX)

- EPA's secure portal for entering and retrieving information
- Facilities will use CDX to gain access to RMP\*eSubmit
- Facilities can use their existing CDX account if they have one

## Useful Definitions in CDX

- Certifiers/Certifying Officials are owners or operators who must certify to the accuracy of the information in the RMP.
   Only a Certifier can submit the RMP.
- Preparers have been granted permission by a facility to access the existing RMP.
   They prepare data for a new or updated RMP. A Preparer cannot submit an RMP.

## Accessing CDX

Navigate to: <a href="https://cdx.epa.gov/">https://cdx.epa.gov/</a>

#### And for assistance:

By Telephone: Person-to-person telephone support is available from 8:00 am to 6:00 pm (EST). Call the toll-free line at 888-890-1995.

By E-mail: Send e-mail to Technical Support at helpdesk@epacdx.net with "Technical Support" in the Subject line.


By Fax:

Assistance requests are accepted 24 hours a day at 703-227-4199. Support personnel will respond to faxed requests Monday through Friday from 8:00 am to 6:00 pm EST/EDT.

## Submittal Steps

- Register the Certifying Official in CDX
- Complete the Electronic Signature
   Agreement (ESA) and mail it to EPA
- Register the "Preparer" and activate RMP eSubmit access in CDX

## RMP\*eSubmit screens are pre-populated with latest RMP if one exists




# RMP\*eSubmit performs additional validations

Preparer



- Correction vs. full resubmission
- Validation of submission type
- Validation of certain date fields based on previous RMP



#### How the RMP Submission Process Will Work

